


LOYALIST COLLEGE

Workplace Inspection Zones - 4, 5, 6, 7, 8a



KEY: ZONE 4 ZONE 5 ZONE 6 ZONE 7 ZONE 8a

Notes: Zone 6 includes the Boiler Room & Tunnel (on First Level)